Deep Water Horizon Oil Spill Incident Action Plan (IAP) Amended/05-09-10 (Field Version)



Operational Period: Operation period 05/08/2010

through 05/12/2010

Starting: 0700 2010/05/08 Ending: 0700 2010/05/12

1. Incid	lent Name	2. Operational Period	ICS 202-EPA
Deep W	/ater Horizon Oil Spill	Operation period 05/08/2010 through	INCIDENT OBJECTIVES
		05/12/2010	
3. Incid	lent Objectives:		
1)	approved site safety plan.	ers and the public by conducting operations in ac	cordance with
2)	Coordinate with Federal, State, Triba	I, and local representatives.	
3)	Conduct water sampling operations to	o determine a baseline in Plaquemines and St. E	Bernard Parish, LA
4)	Conduct sediment sampling operation	n to determine a baseline in Plaquemines and St	Bernard Parish, LA
5)	Conduct air sampling/monitoring ope Bernard Parish, LA.	rations to determine areas of concern in the Plac	uemines and St.
6)	Provide APECT and TAGA support to	areas directed by IC	
•		·	
4. Oper	rational Period Command Emphasis	:	
• • • •	anonari onoa communa zmpnacio	•	
Air s	ampling operations		
, 0	ampining operations		
		. 0	D + /T
5. Prepa	ared by: (Deputy Planning Section Ch	let)	Date / Time
Nicolas	Brescia(EPA)		5/09/2010
	oved by: (Incident Commander)		Date / Time
	,		
Warren	Zehner(EPA)		05/09/2010

ICS 202-EPA

INCIDENT OBJECTIVES

Deep Water Horizon Oil Spill			2. Operational Peri	iod (Date/T	ime)	Assignmen	
			From: 0700, 08 M	lay 10 T	o: 0700, 12 May 10	ICS 204	-EPA
3. Branch Environmental Branch			sion/Group/Staging on Plaquemines				
5. Operations Personnel	Name		Affiliation		Contact # (s)		
Branch Operations Chief:	Warren 2	Zehner	U.S. EPA		214-789-158	5	
Division Supervisor:	Nicolas	Brescia	U.S. EPA		214-789-8383	3	
Division Lead START	Ben Lat	ham	START		972-213-6618	3	
Air Sampling Group Lead START	Jim Wal	llis	START		334-332-7127	7	
6. Resources Assigned			"X" inc	dicates 204	a attachment with additi	ional instructions	s
Strike Team/Task Force/Resource Identifier	Leader		Contact Info. #	# of Persons	Reporting Info/	Notes/Remarks	+
Air Sampling Group Team 1 (Shift 1) (6am - 2pm)	Jim Wallis	334-3	32-7127	2	Contact Div Supervis Lead (START)	or /Division	
Team Members: START (1)	Nata Navarro	361-4	43-5323		Air Sampling Group L	₋ead (START)	
7. Work Assignments							
 Special Instructions Team Supervisors give comms/st Notify Div Sup if any health and s All teams check in no later than 1 	safety issues occur.		I at 0900 and 1200.				
4. All media interest should be direct	ted to Division Supe	ervisor.		brief.			
4. All media interest should be direct 5. Complete 214B at end of shift and 9. Communications (radio and/or Name/Function Warren Zehner, Ops Chief	eted to Division Supe d submit to START	ervisor. team lead nbers nee 585 383					
4. All media interest should be direct 5. Complete 214B at end of shift and 9. Communications (radio and/or page 1) Name/Function Warren Zehner, Ops Chief N. Brescia (EPA), Div Supv Ben Latham, START Div Ld Jim Wallis, START Air Group Ld	phone contact nun Phone 214-789-83	nbers nee					
4. All media interest should be direct 5. Complete 214B at end of shift and 9. Communications (radio and/or page 1) Name/Function Warren Zehner, Ops Chief N. Brescia (EPA), Div Supv Ben Latham, START Div Ld Jim Wallis, START Air Group Ld Jim Wallis, Air Sampling Team 1	phone contact nun Phone 214-789-83 972-213-6	nbers nee 585 383 618					
4. All media interest should be direct 5. Complete 214B at end of shift and 9. Communications (radio and/or page 1) Name/Function Warren Zehner, Ops Chief N. Brescia (EPA), Div Supv Ben Latham, START Div Ld Jim Wallis, START Air Group Ld Jim Wallis, Air Sampling Team 1 Long Ma, IT Support Group Ld	phone contact nun Phone 214-789-1: 214-789-8: 972-213-6 334-332-7	mbers need 585 383 1618 127					
4. All media interest should be direct. 5. Complete 214B at end of shift and	phone contact num Phone 214-789-1: 214-789-8: 972-213-6 334-332-7 972-978-66	nbers nee 585 383 618 127 699					
4. All media interest should be direct 5. Complete 214B at end of shift and 9. Communications (radio and/or page 1) Name/Function Warren Zehner, Ops Chief N. Brescia (EPA), Div Supv Ben Latham, START Div Ld Jim Wallis, START Air Group Ld Jim Wallis, Air Sampling Team 1 Long Ma, IT Support Group Ld Jose Cervantes, MCP/Network Tear Lori Ambrosio, Logistics START Sup	phone contact num Phone 214-789-1: 214-789-3: 972-213-6 334-332-7 972-978-60 poort 248-798-40	nbers nee 585 383 618 127 699					
4. All media interest should be direct 5. Complete 214B at end of shift and 9. Communications (radio and/or page 2) Name/Function Warren Zehner, Ops Chief N. Brescia (EPA), Div Supv Ben Latham, START Div Ld Jim Wallis, START Air Group Ld Jim Wallis, Air Sampling Team 1 Long Ma, IT Support Group Ld Jose Cervantes, MCP/Network Tear Lori Ambrosio, Logistics START Sup Margi Fitzgerald, START Field Cost See communications list for addition	phone contact num Phone 214-789-1: 214-789-8: 972-213-6 334-332-7 972-978-66 972-979-21 poport 248-798-40 Team 225-247-22	nbers nee 585 383 618 127 699					
9. Communications (radio and/or page 2014) Name/Function Warren Zehner, Ops Chief N. Brescia (EPA), Div Supv Ben Latham, START Div Ld Jim Wallis, START Air Group Ld Jim Wallis, Air Sampling Team 1 Long Ma, IT Support Group Ld Jose Cervantes, MCP/Network Tear Lori Ambrosio, Logistics START Sup	phone contact num Phone 214-789-1: 214-789-8: 972-213-6 334-332-7 972-978-66 m 972-979-21 poport 248-798-40 Team 225-247-22 al contact numbers Evacuati	mbers need 585 383 6618 127 699 114 989 264		nent)	Safety Officer	C) Date/T	

1. Incident Name			2. Operational Peri	od (Date/	Γime)	Assignmen	t l ist
Deep Water Horizon Oil Spill			From: 0700 08 M	av 10 T	o: 0700, 12 May 10	ICS 204	
3. Branch		4. Divis	sion/Group/Staging	dy 10 1	0. 0700, 12 May 10		
Environmental Branch		Divisio	on Plaquemines				
5. Operations Personnel	Nam	е	Affiliation		Contact # (s)		
Branch Operations Chief:	Warre	en Zehner	U.S. EPA		214-789-1585	5	
Division Supervisor:	Nicola	as Brescia	U.S. EPA		214-789-8383	3	
Division Lead START	Ben l	_atham	START		972-213-6618	3	
Air Sampling Group Lead START	Jim V	Vallis	START		334-332-7127	•	
6. Resources Assigned			"X" ind	licates 204	a attachment with additi	onal instructions	s
Strike Team/Task Force/Resource Identifier	Leader	(Contact Info. #	# of Persons	Reporting Info/l	Notes/Remarks	+
Air Sampling Group Team 1 (Shift 2) (2pm – 10pm)	Jim Wallis	334-33	32-7127	3	Contact Div Supervise Lead (START)		
Team Members: START (2)	Matt Beer Patrick Wilken		39-7824)2-2001		Air Sampling Group L	ead (START)	
7. Work Assignments							
V05(29.35699 N, 89.45487 Sample for VOCs and PM2 Monitor for VOCs using co 8. Special Instructions 1. Team Supervisors give comms/st 2. Notify Div Sup if any health and s 3. All teams check in no later than 2 4. All media interest should be direct 5. Complete 214B at end of shift and	2.5, Monitor for V lorimetric tubes i atus reports to S afety issues occu 000 at Plaquemined to Division Su	YOC, H2S, CC f VOC action TART Div Ld Jr. nes Division (upervisor.	at 1400 and 1800.				
9. Communications (radio and/or p Name/Function Warren Zehner, Ops Chief N. Brescia (EPA), Div Supv Ben Latham, START Div Ld Jim Wallis, START Air Group Ld Matt Beer, Air Sampling Team 2 Long Ma, IT Support Group Ld Jose Cervantes, MCP/Network Team Lori Ambrosio, Logistics START Sup	Phor 214-789- 214-789 972-213 334-332 248-939 972-978	ne -1585 -8383 -6618 -7127 -7824 8-6699 -2114	ded for this assignm	nent)			
Margi Fitzgerald, START Field Cost See communications list for additiona Emergency Communications							
Medical 911	Evacu	•		_ Other	Safety Officer		
10. Prepared by Deborah Alaniz 30-Dec (Assistant START PSC)		I1. Reviewed Warren Zehne		e/Time	12. Reviewed by (OSC	C) Date/T	ime

3. Branch Environmental Branch 5. Operations Personnel Branch Operations Chief: Division Supervisor: Division Supervisor: Division Lead START Air Sampling Group Lead START Ben Latham STAI Air Sampling Group Lead START Ben Latham STAI Air Sampling Group Lead START G. Resources Assigned Strike Team/Task Force/Resource Identifier Identifier Team Members: Branch (29. 25274 N, 89.35750 W) US COAST GUARD STATION V03(29.31449 N, 89.38433 W) Welding Supply Company, Boothville, LA Sample for VOCs and PM2.5, Monitor for VOC, H2S, CO Monitor for VOCs using colorimetric tubes if VOC action level (10 ppm) is 8. Special Instructions 1. Team Supervisors give comms/status reports to START Div Ld at 0600. 2. Notify Div Sup if any health and safety issues occur. 3. All teams check in no later than 0600 at Division Plaquemines Command Post 4. All media interest should be directed to Division Supervisor. 5. Complete 214B at end of shift and submit to START team lead 9. Communications (radio and/or phone contact numbers needed for this ass Name/Function Warren Zehner, Ops Chief Name, Function Warren, Passana Ben Latham, START Div Ld Prove 214-789-3833 Ben Latham, START Div Ld Prove 214-789-8383 Ben Latham, START Div Ld Prove 248-798-6699 Jose Cervantes, MCP/Network Team Prove 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264	al Period (Date/	Time)	Assignmen	t l ist
3. Branch Environmental Branch 5. Operations Personnel Branch Operations Chief: Warren Zehner U.S. I Division Supervisor: Nicolas Brescia U.S. E Division Lead START Ben Latham STAI Air Sampling Group Lead START Ben Latham STAI 6. Resources Assigned Strike Team/Task Force/Resource Identifier Air Sampling Group Team 2 (Shift 3) (10pm-6am) Team Members: Team Members: Travis Motley 7. Work Assignments 1. Conduct air sampling at the following locations: V02(29.25274 N, 89.35750 W) US COAST GUARD STATION V03(29.31449 N, 89.38433 W) Welding Supply Company, Boothville, LA Sample for VOCs using colorimetric tubes if VOC action level (10 ppm) i 8. Special Instructions 1. Team Supervisors give comms/status reports to START Div Ld at 0600. 2. Notify Div Sup if any health and safety issues occur. 3. All teams check in no later than 0600 at Division Plaquemines Command Post 4. All media interest should be directed to Division Supervisor. 5. Complete 214B at end of shift and submit to START team lead 9. Communications (radio and/or phone contact numbers needed for this as: Name/Function Phone Warren Zehner, Ops Chief 214-789-1585 Name/Function 972-213-6618 Jim Wallis, START Div Ld 972-213-6618 Jim Wallis, START Air Group Ld 334-332-7127 Rob Tichenor, Air Sampling Team 3 832-347-3683 Ben Latham, START Air Group Ld 372-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264	08 May 10	Го: 0700, 12 May 10	ICS 204	-EPA
5. Operations Personnel Branch Operations Chief: Warren Zehner U.S. I. Division Supervisor: Nicolas Brescia U.S. E. Division Lead START Ben Latham STAI Air Sampling Group Lead START Ben Latham STAI Air Sampling Group Lead START Jim Wallis STAF 6. Resources Assigned Strike Team/Task Force/Resource Identifier Leader Contact Info. # Air Sampling Group Team 2 (Shift 3) (10pm-6am) Team Members: Rob Tichenor 832-347-3683 START (2) Travis Motley 979-255-8241 7. Work Assignments 1. Conduct air sampling at the following locations: V02(29.25274 N, 89.35750 W) US COAST GUARD STATION V03(29.31449 N, 89.38433 W) Welding Supply Company, Boothville, Liv V05(29.35699 N, 89.45487 W) Fort Jackson, LA Sample for VOCs and PM2.5, Monitor for VOC, H2S, CO Monitor for VOCs using colorimetric tubes if VOC action level (10 ppm) in 8. Special Instructions 1. Team Supervisors give comms/status reports to START Div Ld at 0600. 2. Notify Div Sup if any health and safety issues occur. 3. All teams check in no later than 0600 at Division Plaquemines Command Post 4. All media interest should be directed to Division Supervisor. 5. Complete 214B at end of shift and submit to START team lead 9. Communications (radio and/or phone contact numbers needed for this as: Name/Function Phone Warren Zehner, Ops Chief 214-789-1585 N. Brescia (EPA), Div Supv 214-789-8383 Ben Latham, START Div Ld 972-213-6618 Jim Wallis, START Air Group Ld 972-978-6699 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications		10. 01 00, 12 May 10		
Branch Operations Chief: Warren Zehner U.S. I Division Supervisor: Nicolas Brescia U.S. E Division Lead START Ben Latham STAI Air Sampling Group Lead START Jim Wallis STAF 6. Resources Assigned Strike Team/Task Force/Resource Identifier Leader Contact Info. # Air Sampling Group Team 2 Jim Wallis 334-332-7127 (Shift 3) (10pm-6am) Team Members: Rob Tichenor Ray-255-8241 7. Work Assignments 1. Conduct air sampling at the following locations: V02(29.25274 N, 89.35750 W) US COAST GUARD STATION V03(29.31449 N, 89.38433 W) Welding Supply Company, Boothville, LAY V05(29.35699 N, 89.45487 W) Fort Jackson, LA Sample for VOCs and PMZ.5, Monitor for VOC, H2S, CO Monitor for VOCs using colorimetric tubes if VOC action level (10 ppm) is 8. Special Instructions 1. Team Supervisors give comms/status reports to START Div Ld at 0600. 2. Notify Div Sup if any health and safety issues occur. 3. All teams check in no later than 0600 at Division Plaquemines Command Post 4. All media interest should be directed to Division Supervisor. 5. Complete 214B at end of shift and submit to START team lead 9. Communications (radio and/or phone contact numbers needed for this as: Name/Function Phone Warren Zehner, Ops Chief 214-789-1585 N. Brescia (EPA), Div Supv 214-789-8383 Ben Latham, START Div Ld 372-978-6618 Jim Wallis, START Air Group Ld 372-978-6689 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications				
Division Supervisor: Division Lead START Air Sampling Group Lead START Ben Latham STAI 6. Resources Assigned Strike Team/Task Force/Resource Identifier Air Sampling Group Team 2 (Shift 3) (10pm-6am) Team Members: Touchuct air sampling at the following locations: V02(29.25274 N, 89.35750 W) US COAST GUARD STATION V03(29.31449 N, 89.38433 W) Welding Supply Company, Boothville, Lead Sample for VOCs and PM2.5, Monitor for VOC, H2S, CO Monitor for VOCs using colorimetric tubes if VOC action level (10 ppm) is 8. Special Instructions 1. Team Supervisors give comms/status reports to START Div Ld at 0600. 2. Notify Div Sup if any health and safety issues occur. 3. All teams check in no later than 0600 at Division Plaquemines Command Post 4. All media interest should be directed to Division Supervisor. 5. Complete 214B at end of shift and submit to START team lead 9. Communications (radio and/or phone contact numbers needed for this as: Name/Function Phone Warren Zehner, Ops Chief N. Brescia (EPA), Div Supv 214-789-8383 Ben Latham, START Div Ld 972-213-6618 Jim Wallis, START air Group Ld 972-978-6699 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications Emergency Communications	ition	Contact # (s)		
Division Lead START Air Sampling Group Lead START Jim Wallis STAF 6. Resources Assigned Strike Team/Task Force/Resource Identifier Air Sampling Group Team 2 (Shift 3) (10pm-6am) Team Members: START (2) Team Members: Provided Assignments 1. Conduct air sampling at the following locations: V02(29.25274 N, 89.35750 W) US COAST GUARD STATION V03(29.31449 N, 89.38433 W) Welding Supply Company, Boothville, Liv V05(29.35699 N, 89.45487 W) Fort Jackson, LA Sample for VOCs and PMZ-5, Monitor for VOC, HZS, CO Monitor for VOCs using colorimetric tubes if VOC action level (10 ppm) if 8. Special Instructions 1. Team Supervisors give comms/status reports to START Div Ld at 0600. 2. Notify Div Sup if any health and safety issues occur. 3. All teams check in no later than 0600 at Division Plaquemines Command Post 4. All media interest should be directed to Division Supervisor. 5. Complete 214B at end of shift and submit to START team lead 9. Communications (radio and/or phone contact numbers needed for this as: Name/Function Phone Warren Zehner, Ops Chief 214-789-1585 N. Brescia (EPA), Div Supv 214-789-8383 Ben Latham, START Div Ld 334-332-7127 Rob Tichenor, Air Sampling Team 3 832-347-36683 Long Ma, IT Support Group Ld 972-978-6699 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264	EPA	214-789-1585	5	
Air Sampling Group Lead START Jim Wallis STAR 6. Resources Assigned Strike Team/Task Force/Resource Identifier Air Sampling Group Team 2 (Shift 3) (10pm-6am) Team Members: START (2) 7. Work Assignments 1. Conduct air sampling at the following locations: V02(29.25274 N, 89.35750 W) US COAST GUARD STATION V03(29.31449 N, 89.38433 W) Welding Supply Company, Boothville, Live V05(29.35699 N, 89.45487 W) Fort Jackson, LA Sample for VOCs and PM2.5, Monitor for VOC, H2S, CO Monitor for VOCs using colorimetric tubes if VOC action level (10 ppm) if the special Instructions 1. Team Supervisors give comms/status reports to START Div Ld at 0600. 2. Notify Div Sup if any health and safety issues occur. 3. All teams check in no later than 0600 at Division Plaquemines Command Post 4. All media interest should be directed to Division Supervisor. 5. Complete 214B at end of shift and submit to START team lead 9. Communications (radio and/or phone contact numbers needed for this as: Name/Function Phone Warren Zehner, Ops Chief 214-789-1585 N. Brescia (EPA), Div Supv 214-789-8383 Ben Latham, START Div Ld 972-213-6618 Jim Wallis, START Air Group Ld 972-978-6699 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications	EPA	214-789-8383	3	
6. Resources Assigned Strike Team/Task Force/Resource Identifier Air Sampling Group Team 2 (Shift 3) (10pm-6am) Team Members: START (2) 7. Work Assignments 1. Conduct air sampling at the following locations: V02(29.25274 N, 89.35750 W) US COAST GUARD STATION V03(29.31449 N, 89.38750 W) US COAST GUARD STATION V05(29.35699 N, 89.45487 W) Fort Jackson, LA Sample for VOCs and PM2.5, Monitor for VOC, H2S, CO Monitor for VOCs using colorimetric tubes if VOC action level (10 ppm) is 8. Special Instructions 1. Team Supervisors give comms/status reports to START Div Ld at 0600. 2. Notify Div Sup if any health and safety issues occur. 3. All teams check in no later than 0600 at Division Plaquemines Command Post 4. All media interest should be directed to Division Supervisor. 5. Complete 214B at end of shift and submit to START team lead 9. Communications (radio and/or phone contact numbers needed for this as: Name/Function Phone Warren Zehner, Ops Chief Phone Warren Zehner, Ops C	ART	972-213-6618	3	
Strike Team/Task Force/Resource Identifier Air Sampling Group Team 2 (Shift 3) (10pm-6am) Team Members: Rob Tichenor Travis Motley 979-255-8241 7. Work Assignments 1. Conduct air sampling at the following locations: V02(29.25274 N, 89.35750 W) US COAST GUARD STATION V03(29.31449 N, 89.38433 W) Welding Supply Company, Boothville, Le V05(29.35699 N, 89.45487 W) Fort Jackson, LA Sample for VOCs and PMZ.5, Monitor for VOC, HZS, CO Monitor for VOCs using colorimetric tubes if VOC action level (10 ppm) is 8. Special Instructions 1. Team Supervisors give comms/status reports to START Div Ld at 0600. 2. Notify Div Sup if any health and safety issues occur. 3. All teams check in no later than 0600 at Division Plaquemines Command Post 4. All media interest should be directed to Division Supervisor. 5. Complete 214B at end of shift and submit to START team lead 9. Communications (radio and/or phone contact numbers needed for this as: Name/Function Phone Warren Zehner, Ops Chief 214-789-1585 Na Brescia (EPA), Div Supv 214-789-8383 Ben Latham, START Div Ld 972-213-6618 Jim Wallis, START Air Group Ld 334-332-7127 Rob Tichenor, Air Sampling Team 3 832-347-3683 Long Ma, IT Support Group Ld 972-978-6699 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications	RT	334-332-7127	•	
Air Sampling Group Team 2 (Shift 3) (10pm-6am) Team Members: Rob Tichenor Ray-255-8241 7. Work Assignments 1. Conduct air sampling at the following locations: V02(29.25274 N, 89.35750 W) US COAST GUARD STATION V03(29.31449 N, 89.38433 W) Welding Supply Company, Boothville, LAY-05(29.35699 N, 89.45487 W) Fort Jackson, LA Sample for VOCs and PM2.5, Monitor for VOC, H2S, CO Monitor for VOCs using colorimetric tubes if VOC action level (10 ppm) is 8. Special Instructions 1. Team Supervisors give comms/status reports to START Div Ld at 0600. 2. Notify Div Sup if any health and safety issues occur. 3. All teams check in no later than 0600 at Division Plaquemines Command Post 4. All media interest should be directed to Division Plaquemines Command Post 4. All media interest should be directed to Division Supervisor. 5. Complete 214B at end of shift and submit to START team lead 9. Communications (radio and/or phone contact numbers needed for this as: Name/Function Phone Warren Zehner, Ops Chief 214-789-1585 N. Brescia (EPA), Div Supv 214-789-8383 Ben Latham, START Div Ld 972-213-6618 Jim Wallis, START Air Group Ld 334-332-7127 Rob Tichenor, Air Sampling Team 3 832-347-3683 Long Ma, IT Support Group Ld 972-978-6699 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications	"X" indicates 204	4a attachment with additi	onal instruction	s
Chift 3) (10pm-6am) Rob Tichenor Travis Motley Rob Tichenor Rob Tichenor Travis Motley Rob Tichenor Rob	# of Persons	Reporting Info/l	Notes/Remarks	+
7. Work Assignments 1. Conduct air sampling at the following locations:	3	Contact Div Supervise Lead (START	or /Division	
7. Work Assignments 1. Conduct air sampling at the following locations: V02(29.25274 N, 89.35750 W) US COAST GUARD STATION V03(29.31449 N, 89.38433 W) Welding Supply Company, Boothville, LA V05(29.35699 N, 89.45487 W) Fort Jackson, LA Sample for VOCs and PM2.5, Monitor for VOC, H2S, CO Monitor for VOCs using colorimetric tubes if VOC action level (10 ppm) is supervisors give comms/status reports to START Div Ld at 0600. 2. Notify Div Sup if any health and safety issues occur. 3. All teams check in no later than 0600 at Division Plaquemines Command Post All media interest should be directed to Division Supervisor. 5. Complete 214B at end of shift and submit to START team lead 9. Communications (radio and/or phone contact numbers needed for this as: Name/Function Phone Warren Zehner, Ops Chief N. Brescia (EPA), Div Supv 214-789-8383 Ben Latham, START Div Ld Jim Wallis, START Div Ld Jim Wallis, START Air Group Ld 334-332-7127 Rob Tichenor, Air Sampling Team 3 832-347-3683 Long Ma, IT Support Group Ld 972-978-6699 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264		Air Sampling Group L	ead (START)	
1. Conduct air sampling at the following locations:			, ,	
1. Conduct air sampling at the following locations: \text{V02}(29.25274 N, 89.35750 W) US COAST GUARD STATION \text{V03}(29.31449 N, 89.38433 W) Welding Supply Company, Boothville, LA V05(29.35699 N, 89.45487 W) Fort Jackson, LA Sample for VOCs and PM2.5, Monitor for VOC, H2S, CO Monitor for VOCs using colorimetric tubes if VOC action level (10 ppm) is 8. Special Instructions 1. Team Supervisors give comms/status reports to START Div Ld at 0600. 2. Notify Div Sup if any health and safety issues occur. 3. All teams check in no later than 0600 at Division Plaquemines Command Post 4. All media interest should be directed to Division Supervisor. 5. Complete 214B at end of shift and submit to START team lead 9. Communications (radio and/or phone contact numbers needed for this as: Name/Function Phone Warren Zehner, Ops Chief 214-789-1585 N. Brescia (EPA), Div Supv 214-789-8383 Ben Latham, START Div Ld 972-213-6618 Jim Wallis, START Air Group Ld 334-332-7127 Rob Tichenor, Air Sampling Team 3 832-347-3683 Long Ma, IT Support Group Ld 972-978-6699 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications				
9. Communications (radio and/or phone contact numbers needed for this as: Name/Function Phone Warren Zehner, Ops Chief 214-789-1585 N. Brescia (EPA), Div Supv 214-789-8383 Ben Latham, START Div Ld 972-213-6618 Jim Wallis, START Air Group Ld 334-332-7127 Rob Tichenor, Air Sampling Team 3 832-347-3683 Long Ma, IT Support Group Ld 972-978-6699 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications	for debrief.			
Name/Function Phone Warren Zehner, Ops Chief 214-789-1585 N. Brescia (EPA), Div Supv 214-789-8383 Ben Latham, START Div Ld 972-213-6618 Jim Wallis, START Air Group Ld 334-332-7127 Rob Tichenor, Air Sampling Team 3 832-347-3683 Long Ma, IT Support Group Ld 972-978-6699 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications				
Warren Zehner, Ops Chief 214-789-1585 N. Brescia (EPA), Div Supv 214-789-8383 Ben Latham, START Div Ld 972-213-6618 Jim Wallis, START Air Group Ld 334-332-7127 Rob Tichenor, Air Sampling Team 3 832-347-3683 Long Ma, IT Support Group Ld 972-978-6699 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications	ssignment)			
N. Brescia (EPA), Div Supv 214-789-8383 Ben Latham, START Div Ld 972-213-6618 Jim Wallis, START Air Group Ld 334-332-7127 Rob Tichenor, Air Sampling Team 3 Long Ma, IT Support Group Ld 972-978-6699 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications				
Ben Latham, START Div Ld 972-213-6618 Jim Wallis, START Air Group Ld 334-332-7127 Rob Tichenor, Air Sampling Team 3 832-347-3683 Long Ma, IT Support Group Ld 972-978-6699 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications				
Jim Wallis, START Air Group Ld Rob Tichenor, Air Sampling Team 3 Long Ma, IT Support Group Ld Jose Cervantes, MCP/Network Team Lori Ambrosio, Logistics START Support Margi Fitzgerald, START Field Cost Team See communications list for additional contact numbers Emergency Communications				
Long Ma, IT Support Group Ld 972-978-6699 Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications				
Jose Cervantes, MCP/Network Team 972-979-2114 Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications				
Lori Ambrosio, Logistics START Support 248-798-4089 Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications				
Margi Fitzgerald, START Field Cost Team 225-247-2264 See communications list for additional contact numbers Emergency Communications				
See communications list for additional contact numbers Emergency Communications				
Emergency Communications				
Modical 044				
Medical 911 Evacuation	Other	Safety Officer		
10. Prepared byDate/Time11. Reviewed by (PSC)Deborah Alaniz30-Dec-10 / 15:50Warren Zehner, PSC(Assistant START PSC)	Date/Time	12. Reviewed by (OSC	C) Date/T	ime

1. Incident Name			2. Operational Per	iod (Date/	Time)	Assignmen	t List
Deep Water Horizon Oil Spill			From: 0700, 08 N	May 10	Го: 0700, 12 May 10	ICS 204	
3. Branch			sion/Group/Staging		,		
Environmental Branch		TAGA	Group				
5. Operations Personnel	Name	1	Affiliation		Contact # (s)		
Branch Operations Chief:	Warren 2	Zehner	U.S. EPA		214-789-1585	5	
Division Lead START	Ben Lat	ham	START		972-213-6618	3	
Air Sampling Group Lead START	Jim Wal	lis	START		334-332-7127	•	
6. Resources Assigned			"X" in	dicates 204	4a attachment with additi	onal instruction	s
Strike Team/Task Force/Resource Identifier	Leader		Contact Info. #	# of Persons	Reporting Info/	Notes/Remarks	, +
Air Sampling Group Team 3 (TAGA)	Royse Harris	806-6	676-7674	2	Contact group Super	visor START	
Team Members: START (1)	Kay Harris	806-6	681-9989				
7. Work Assignments		•		•			•
 Conduct regular functional V02(29.25274 N, 89.3575) V03(29.31449 N, 89.3843) V05(29.35699 N, 89.4548) Respond to odor complain Notify START team lead of 	0 W) US COAST G 3 W) Welding Supp 7 W) Fort Jackson, ats, collect 1: air san	JARD ST y Compa LA nple; trans	ATION ny, Boothville, LA sport to TAGA for ana		ng stations:		
8. Special Instructions							
Team Supervisors give comms/s Notify Div Sup if any health and s All teams check in no later than s All media interest should be direct 9. Communications (radio and/or	safety issues occur. 1930 at Placquemin ted to Division Supe	es Divisio ervisor.	on Command Post for				
9. Communications (radio and/or Name/Function	pnone contact nur Phone	nbers nee	eded for this assigni	nent)			
Warren Zehner, Ops Chief	214-789-15	85					
N. Brescia (EPA), Div Supv	214-789-8						
Ben Latham, START Div Ld	972-213-66	818					
Jim Wallis, START Air Group Ld	334-332-7	27					
Long Ma, IT Support Group Ld	972-978-6	699					
Jose Cervantes, MCP/Network Tear	n 972-979-2	114					
Lori Ambrosio, Logistics START Sup	•						
Margi Fitzgerald, START Field Cost	Team 225-247-22	64					
See communications list for addition Emergency Communications	al contact numbers						
Medical 911	Evacuati			Other	Safety Officer		
10. Prepared by Deborah Alaniz 30-Dec (Assistant START PSC)		Reviewe rren Zehn	, ,	te/Time	12. Reviewed by (OSC	C) Date/T	Γime

1. Incident Name			2. Operational Peri	iod (Date	/Time)	Assignmen	f Liet
Deep Water Horizon Oil Spill			-	•	To: 0700, 12 May 10	ICS 204	
3. Branch			sion/Group/Staging	.u, .u			
Environmental Branch		Divisio	n Plaquemines				
5. Operations Personnel	Na	ame	Affiliation		Contact # (s)		
Branch Operations Chief:	War	en Zehne	er U.S. E	PA	214-789	-1585	
Division Supervisor:	Nicol	as Bresci	a U.S. E	PA	214-789	-8383	
Division Lead START	Ben	Latham	STAF	RT	972-213	3-6618	
6. Resources Assigned			"X" inc	dicates 20	4a attachment with additi	onal instructions	s
Strike Team/Task Force/Resource Identifier	Leader		Contact Info. #	# of Persons	Reporting Info/	Notes/Remarks	\
Support Group	Ben Latham	972-2	13-6618	5			
MCP/Network Team START (1)	Jose Cervantes	972-9	79-2114				
START (I)							
Data Management Team	Long Ma	972-9	78-6699				
START (1)	Lori Ambrosio	248-7	98-4089				
Logistics/Resource Team							
START (1)	Margie Fitzgerald	225-2	47-2264				
Field Cost Team	Margie i itzgeraid	225-2	47-2204				
START (1)							
7. Work Assignments							
Conduct support operation	ns to Division Comm	and Staff	and all field teams.				
Conduct logistics support	to MCP and all field	operations	S.				
Provide field accounting s	upport for cost docu	mentation	•				
8. Special Instructions							
 Team Supervisors give comms/s Notify Div Sup if any health and s 		RT Div Ld	at 1000 and 1500.				
3. All teams check in no later than 2	000 at Placquemine		Command Post for d	lebrief.			
4. All media interest should be direct	ted to Division Supe	rvisor.					
9. Communications (radio and/or		bers nee	ded for this assignn	nent)			
Name/Function Warren Zehner, Ops Chief	Phone 214-789-15	95					
N. Brescia (EPA), Div Supv	214-789-83						
Ben Latham, START Div Ld	972-213-66						
Jim Wallis, Air Sampling Group Ld	334-332-71	27					
See communications list for addition Emergency Communications	al contact numbers						
Medical 911	Evacuation	on		_ Other	Safety Officer		
10. Prepared by			, ,	te/Time	12. Reviewed by (OSC) Date/T	ime
Deborah Alaniz 30-Dec (Assistant START PSC)	:-10 / 15:50 Wai	ren Zehne	er, PSC				
(ASSISTANT FOO)					<u> </u>		

1. Incident Name 2. Operational Period (Date/Time)				ime)	Assignmen	nt List		
Deep Water Horizon Oil Spill			From: 0700), 08 May 10	Т	o: 0700, 12 May 10	ICS 204	
3. Branch			sion/Group/St	aging				
Environmental Branch		Divisio	on Chaimette					
5. Operations Personnel	Nam	е	Affil	iation		Contact # (s)		
Branch Operations Chief: Division Supervisor:		en Zehner en Zehner			214-789-1585 214-789-1585			
Division Lead START	Davi	d Bordelon	STA	\RT		972-213-6618	3	
Air Sampling Group Lead START	Tom	Davis	ST	ART		484-880-5113	3	
6. Resources Assigned				"X" indicates	204	a attachment with additi	onal instruction	ıs
Strike Team/Task Force/Resource Identifier	Leader		Contact Info. #	# c		Reporting Info/	Notes/Remarks	, ↓
Air Sampling Group Team 1 (Shift 1) (1800 - 0200)	Mark Wilson	337-5	581-8430	2		Contact Div Supervisor/I Lead(START)	Division	
Team Members:	Warren Silveri	a 302-4	162-0164			Air Sampling Group Lea	d (START)	
START (1)	VValler Oliver	002	102 0104				- (,	
7. Work Assignments								
 Conduct air sampling at th C01 (29.94562 N, 89.9721 			ear the corner	of Jackson Str	eet s	and Judge Perez, Chaln	nette I.A	
C02 (29.86609 N, 89.8910	08 W) Fire Statio	n number 8,	Poydras LA		001	and dauge i croz, chair	notto, Er	
C03 (29.82209 N, 89.6086 Sample for VOCs and PM				lale, LA				
Monitor for VOCs using co) is exceeded				
8. Special Instructions								
Team Supervisors give comms/st	tatus raparts to	STADT Div.L.	4 24 0330					
Notify Div Sup if any health and s			at 0250.					
 All teams check in at 1800 and 02 All media interest should be direct 			mmand Post fo	r debrief.				
Complete 214B at end of shift and			l.					
·								
9. Communications (radio and/or	phone contact	numbers nee	eded for this a	ssignment)				
Name/Function	Pho							
Warren Zehner, Ops Chief/Div Supv	214-789	-1585						
David Bordelon, START Div Ld	225-772	-7921						
Tom Davis, START Air Group Ld	484-880	0-5113						
Matt Beer, Air Sampling Team 1	248-939	9-7824						
Janine Latham, IT Group Ld	215-62	0-5664						
Greg Thomason, IT Support Group I								
Jose Cervantes, MCP/Network Tean								
Jean Brown, START Field Cost Tear	m 404-406	o-2813						
See communications list for addition	al contact numb	ers						
Emergency Communications								
Medical 911		uation	(555)			Safety Officer		
10. Prepared by David Bordelon 30-Dec		11. Reviewe Warren Zehn		Date/Time	•	12. Reviewed by (OSC	Date/	Time
David Doldelon 30-Dec	5-10 / 10.00	vvalitil ZEIII	ici, i 00					

1. Incident Name			2. Operational Per	iod (Date/	Time)	Assignmen	t List
Deep Water Horizon Oil Spill			From: 0700, 08 M	lay 10 T	o: 0700, 12 May 10	ICS 204	
3. Branch			sion/Group/Staging			•	
Environmental Branch		DIVISIO	on Chaimette				
5. Operations Personnel	Name		Affiliation		Contact # (s)		
Branch Operations Chief: Division Supervisor:	Warren Z Warren Z		U.S. EPA U.S. EPA		214-789-1585 214-789-1585		
Division Lead START	David Bo	rdelon	START		972-213-6618	3	
Air Sampling Group Lead START	Tom Day	ris	START		484-880-5113	3	
6. Resources Assigned			"X" inc	dicates 204	la attachment with additi	onal instruction	ıs
Strike Team/Task Force/Resource Identifier	Leader		Contact Info. #	# of Persons	Reporting Info/	Notes/Remarks	, ♦
Air Sampling Group Team 2 (Shift 2) (0200 - 1000)	Pat Turner	843-4	69-5811	2	Contact Div Supervisor/I Lead(START)	Division	
Team Members:	Terry Alexander	410-9	19-8319		Air Sampling Group Lea	d (START)	
START (1)	, only ruerande.	1.00				,	
7. Work Assignments							
1. Conduct air sampling at th C01 (29.94562 N, 89.9721 C02 (29.86609 N, 89.8910 C03 (29.82209 N, 89.6086 Sample for VOCs and PM Monitor for VOCs using complete and the Complete Service of Service o	I W) Fire Station num 8 W) Fire Station num 8 W) Fire Station num 62 W) Emergency Op 2.5, Monitor for VOC blorimetric tubes if VO tatus reports to STAF afety issues occur. 000 at Division Chalr ated to Division Supe	nber 3, nember 8, Ferations and PM DC action	Poydras LA Center, Hopedale, LA 10 I level (10 ppm) is exc I at 0600 and 1000.	eeded	and Judge Perez, Chaln	nette, LA	
9. Communications (radio and/or Name/Function	phone contact num Phone	bers nee	eded for this assignn	nent)			
Warren Zehner, Ops Chief/Div Supv	214-789-15	85					
David Bordelon, START Div Ld	225-772-79	21					
Tom Davis, START Air Group Ld	484-880-51	13					
Matt Beer, Air Sampling Team 1	248-939-782	24					
Janine Latham, IT Group Ld	215-620-56	64					
Greg Thomason, IT Support Group I							
Jose Cervantes, MCP/Network Tear							
Jean Brown, START Field Cost Tea	m 404-406-28 ²	13					
See communications list for addition Emergency Communications	al contact numbers						
Medical 911	Evacuation	n		Other	Safety Officer		
10. Prepared by		_	d by (PSC) Da	te/Time	12. Reviewed by (OSC) Date/1	Гіте
David Bordelon 30-Dec	:-10 / 15:50 War	ren Zehn	er, PSC				

1. Incident Name			2. Operational Period (Date/Time)			Assignment List	
Deep Water Horizon Oil Spill			From: 0700, 08 M	ay 10 T	o: 0700, 12 May 10	IČS 204-EPA	
3. Branch Environmental Branch			sion/Group/Staging n Chalmette	•			
5. Operations Personnel	Name		Affiliation		Contact # (s)		
Branch Operations Chief: Division Supervisor:	Warren Z Warren Z		U.S. EPA U.S. EPA		214-789-1585 214-789-1585		
Division Lead START	David Bo	ordelon	START		972-213-6618	3	
Air Sampling Group Lead START	Tom Dav	⁄is	START		484-880-5113	3	
6. Resources Assigned			"X" inc	licates 204	a attachment with additi	onal instructions	
Strike Team/Task Force/Resource Identifier	Leader		Contact Info. #	# of Persons	Reporting Info/	Notes/Remarks	
Air Sampling Group Team 3 (Shift 3) (1000-1800 Shift)	Jeremy Wood	334-66	63-3886	2	Contact Div Supervisor/I Lead(START)	Division	
Team Members: START (1)	Claire Odenweller	937-47	75-1626		Air Sampling Group Lea	d (START)	
7. Work Assignments 1. Conduct air sampling at th	W) Fire Station nur 08 W) Fire Station nu 62 W) Emergency Op 2.5, Monitor for VOC	nber 3, ne imber 8, F peratoins (and PM1	Poydras LA Center, Hopedale, LA 0		and Judge Perez, Chalr	nette, LA	
 Team Supervisors give comms/st Notify Div Sup if any health and s All teams check in at 1000 and 18 All media interest should be direct Complete 214B at end of shift and 	afety issues occur. 800 at Division Chalr ted to Division Supe d submit to START t	nette Con rvisor. eam lead.	nmand Post for debrie				
9. Communications (radio and/or p		bers nee	ded for this assignm	nent)			
Name/Function	Phone	0.5					
Warren Zehner, Ops Chief/Div Supv							
David Bordelon, START Div Ld Tom Davis, START Air Group Ld	225-772-79 484-880-51						
Matt Beer, Air Sampling Team 1	248-939-78						
Janine Latham, IT Group Ld	215-620-56						
Greg Thomason, IT Suport Group Lo		-					
, ,							
Jose Cervantes, MCP/Network Tean Jean Brown, START Field Cost Tear							
Coan Brown, Crart Flora Cook Foal	101 100 20						
See communications list for additions	al contact numbers						
Emergency Communications Medical 911	Evacuation	vn.		Other	Safety Officer		
10. Prepared by	Evacuation Date/Time 11.		I by (PSC) Dat	e/Time	Safety Officer 12. Reviewed by (OSC	Date/Time	
		ren Zehne		.e/ i iiiie	12. Reviewed by (USC	o) Date/Time	

			2. Operational Peri From: 0700, 08 M	•	ime) o: 0700, 12 May 10	Assignmer ICS 204	
3. Branch Environmental Branch			sion/Group/Staging on Chalmette	dy 10 1	5. 0700, 12 May 10	L	
5. Operations Personnel	Nar	me	Affiliation		Contact # (s)		
Branch Operations Chief: Division Supervisor:	Warren Ze Warren Ze		U.S. EPA U.S. EPA		214-789-1585 214-789-1585		
Division Lead START	David Bor	rdelon	START		972-213-6618	8	
Water Sampling Group Lead START	Curtis Fra	anklin	START		817-229-1222	2	
6. Resources Assigned			"X" inc	licates 204a	a attachment with additi	ional instruction	s
Strike Team/Task Force/Resource	Leader		Contact Info. #	# of	Reporting Info/	Notes/Remarks	, 🔻
Identifier Water Sampling Group Team 1	Curtis Franklin		29-1222	Persons 3	Contact Div Supervisor/I Lead(START)		
Team Members: START (2)	Jarrod Redwine Jeff Bryniarski		38-2464 84-2490		Water Sampling Group L	_ead (START)	
8. Special Instructions							
 Team Supervisors give comms/s Notify Div Sup if any health and s All teams check in no later than 2 All media interest should be direct 	safety issues occur. 2000 at Division Chalr	mette Co		ief.			
 Notify Div Sup if any health and s All teams check in no later than 2 	phone contact number Phone 214-789-158 225-772-792 P. Ld 817-229-122 am 1 248-939-782-215-620-566 512-417-554 972-979-211 do 404-406-281	mette Corvisor. Ders nee 35 21 22 4 34 34	ommand Post for debr				
2. Notify Div Sup if any health and s 3. All teams check in no later than 2 4. All media interest should be direct 9. Communications (radio and/or p Name/Function Warren Zehner, Ops Chief/Div Supv David Bordelon, START Div Ld Curtis Franklin, START Water Group Jarrod Redwine, Water Sampling Te Janine Latham, IT Group Ld Greg Thomason, IT Suport Group Ld Jose Cervantes, MCP/Network Team Jean Brown, START Field Cost Tear See communications list for additional	phone contact number Phone 214-789-158 225-772-792 P. Ld 817-229-122 am 1 248-939-782-215-620-566 512-417-554 972-979-211 do 404-406-281	mette Corvisor. Deers nee	ommand Post for debr	nent)	Safety Officer		



